


WESTERN AVE



←
#24

NEW
CLEANOUT INSTALLED

Approx 18 ft up from cleanout
is where blockage found.

GARAGE

LAT 42.302586

red dot

LONG -70.910866

26 Western Ave Garage

Hull Waste Water



GPS Coordinates with Google Maps

Latitude and longitude of an address

Convert an address or a place to lat long: fill the address field and click on "Get GPS Coordinates" to display its latitude and longitude. Read the result provided by the converter on the left column or directly on the map.

AdChoices GPS Coordinates Latitude and Longitude Map Coordinates Address


Find an address from its GPS coordinates

Address from decimal coordinates: fill the decimal GPS coordinates and click on the corresponding "Get Address" button.

Address from sexagesimal coordinates: fill the sexagesimal GPS coordinates and click on the corresponding "Get Address" button.

Latitude, longitude and address of any point on Google Maps

Click directly on the map to get an address and its GPS coordinates. The latitude coordinate and the longitude coordinate are displayed on the left column and on the map.



HACH Company

Complete water analysis solutions. Research and order products online!

Address

26 Western Ave, Hull, MA 02045, USA

Get GPS Coordinates

DD (decimal degrees)*

Latitude

42.30252309999999

Longitude

-70.9108372

Get Address

DMS (degrees, minutes, secondes)*


Latitude

☒ N ☐ S
 42 ° 18 ' 9.083 "

Longitude

☐ E ☒ W
 70 ° 54 ' 39.013 "

Get Address




▶

**GET A
FREE TRADE-IN VALUE
IN SECONDS!**

CLICK HERE

▶



correct.top.com/Cyber/Sales/Save-Big

* World Geodetic System 84 (WGS 84)

Street View

Interested in watching Street View in action alongside different types of Google Maps, all synchronized? Check out our maps project (<https://www.mapsview.net/>)!



Work Order - Backup or Blockage Call

Hull Wastewater

Work Order Information

Date:	01/05/2017	Type:	Corrective Maintenance	Status:	Completed
Asset:	22 - WW - sewers/pipes/force mains	Priority:	Normal	Reason:	Service Call

Description of Issue

Description: 26 Western Ave final blockage repair day

Notes: HUB construction excavation to sewer main and Rasano Davis jetter work. With W&C staff and camera work.

Actions Taken


Staff: Outside Contractor

Service: Excavation downstream of #26 found blockage just upstream between house and excavation. Cleared line of grease and debris full blockage. Camera confirmed line was cleared + die tested. HUB installed cleanout port for better access to this area for preventive maintenance or camera.

Photos



Cleanout facing upstream to grade



Blockage seen from camera